

**LOCATION # 1**  
MAP # 819-813  
*No Discrepancy*


Pic # 1375  
Aerial



**LOCATION # 4**  
MAP # 819-811

Pic # 1307  
Aerial

*Reframe pole - reattachment or new*



**LOCATION # 2**  
MAP # 818-814  
*Un-terminated port*

Pic # 1242  
UG



**LOCATION # 5**  
MAP # 819-811

Pic # 1157  
Aerial

*Un-terminated port*



**LOCATION # 3**  
MAP # 819-812  
*No Discrepancy*

Pic # 1358  
UG



**LOCATION # 6**  
MAP # 819-811

Pic # 1175  
Aerial

*Remove old power supply*



**LOCATION # 15**  
MAP # 819-814  
*No Discrepancy*

Pic # 1218  
UG



**LOCATION # 17**  
MAP # 819-814  
*No Discrepancy*

Pic # 1247  
UG



**LOCATION # 15.1**  
MAP # 819-814  
*Missing lockinator*

Pic # 1219  
UG



**LOCATION # 18**  
MAP # 819-814  
*No Discrepancy*

Pic # 1221  
UG



**LOCATION # 16**  
MAP # 819-814  
*No Discrepancy*

Pic # 1220  
UG



**LOCATION # 19**  
MAP # 819-814  
*No Discrepancy*

Pic # 1222  
UG

